

HST #837181627

DATE 2017-09-08	TECHNICIAN Darren Mann		JOB/ORDER # 7684	REFERENCE TEXT Client reference	
FIRST NAME Hadi		LAST NAME Golkarieh			
BILLING ADDRESS COMPANY / BILLING NAME 1515 HOMER MEWS VANCOUVER, V6Z3E8 BRITISH COLUMBIA, CANA		10	SERVICE ADDRES 408 - 256 EAST 2N VANCOUVER, BRITISH COLUMBI	DAVE	
PHONE 604.710.0548			EMAIL hadigol@gmail.com	EMAIL hadigol@gmail.com	

REASON FOR TODAY'S CALL: Garburator leaking

## **DESCRIPTION OF WORK PERFORMED:**

The garburator was leaking through the bottom and could not be repaired. I replaced the garburator with new and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION			PRICE
1		Supply & Install 1/2HP Badger5 Garburator			\$319.00
invoice and tell us how we did.		endlack"	IARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$319.00
			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$15.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$334.95
		we did.	MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,		

Thank You!

2017-09-08

CUSTOMER SIGNATURE

SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

DATE