



DATE 2017-09-13	TECHNICIAN Darren Mann	JOB/ORDER # 7698	REFERENCE TEXT Client reference
FIRST NAME Carmella		LAST NAME Politano	
BILLING ADDRESS COMPANY / BILLING NAME 502 - 1323 HOMER ST VANCOUVER, BC, V6B 5T1 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 502 - 1323 HOMER ST, BUZZER 188 VANCOUVER, BC, V6B 5T1 BRITISH COLUMBIA, CANADA	
PHONE 778-228-8705		EMAIL cpolitano@bclc.com	

REASON FOR TODAY'S CALL:  
tub/shower won't fully shut off.


DESCRIPTION OF WORK PERFORMED:  
I replaced the mixing & pressure balances cartridges within the shower valve and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Mixing & Pressure Balance Cartridges - Kohler	\$259.00	\$259.00
			SUBTOTAL:	\$259.00
			GST (5%):	\$12.95
			TOTAL:	\$271.95

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

**WARRANTY:** **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY  
**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

  
 \_\_\_\_\_  
 CUSTOMER SIGNATURE

2017-09-13  
 \_\_\_\_\_  
 DATE