



DATE 2017-09-15	TECHNICIAN Darren Mann	JOB/ORDER # 7711	REFERENCE TEXT Client reference
FIRST NAME Julie		LAST NAME Robinson	
BILLING ADDRESS COMPANY / BILLING NAME 1408 - 1500 HORNBY ST. VANCOUVER, V6Z 2R1 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1408 - 1500 HORNBY ST. BUZ#2118 VANCOUVER, V6Z 2R1 BRITISH COLUMBIA, CANADA	
PHONE 604.803.2393		EMAIL julie.robinson@gov.bc.ca	

REASON FOR TODAY'S CALL:
garburator leaking


DESCRIPTION OF WORK PERFORMED:
The garburator housing deteriorated to the point that it fell right off the mounting bracket. I replaced the garburator with new and tested by filling and draining both sides of the sink while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Badger5 Garburator	\$319.00	\$319.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



 CUSTOMER SIGNATURE

2017-09-15

 DATE

SUBTOTAL:	\$319.00
GST (5%):	\$15.95
TOTAL:	\$334.95