

🕒 @SimplyPlumbing 🛛 🚹 YaletownPlumbing

HST #837181627

DATE 2017-09-19	TECHNICIAN Darren Mann		JOB/ORDER # 7715		REFERENCE TEXT Client reference
FIRST NAME Angeles		LAST NAME Contarbio	7		
BILLING ADDRESS COMPANY / BILLING NAME 3207 - 602 CITADEL PARADE VANCOUVER, V6B1X2 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 3207 - 602 CITADEL PARADE BUZZER: 8251 VANCOUVER, V6B1X2 BRITISH COLUMBIA, CANADA	
PHONE 778.389.4133				EMAIL angelescontarbio@gmail.com	

REASON FOR TODAY'S CALL:

The garbage disposal system is not working. We switch it on but nothing happens, it appears as if it went dead.

## DESCRIPTION OF WORK PERFORMED:

I was able to unjam the garburator by removing what appeared to be a small pebble. Tested by filling and draining the sink while running the garburator.

QTY.	CODE	DESCRIPTION					PRICE
1		Labour	7			\$109.00	\$109.00
Gwe us Feedback			WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT		SUBTOTAL:	\$109.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			GST (5%):			\$5.45	
		INTEREST AT	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$114.45		
		MATERIALS L SETTLED, RU RESULTING F <u>TERMS</u> : NET	MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETULED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES CHARGES. E. & O. E. CHARGES. E. & O. E. CUSTOMER SIGNATURE DATIONAL DATE: DATE: DATE				