



DATE 2017-09-19	TECHNICIAN Darren Mann	JOB/ORDER # 7736	REFERENCE TEXT
FIRST NAME Aleta		LAST NAME Brown	
BILLING ADDRESS 2307 - 233 ROBSON ST VANCOUVER, V6B0E8 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2307 - 233 ROBSON ST, BUZZER 7195 VANCOUVER, V6B0E8 BRITISH COLUMBIA, CANADA	
PHONE 778.792.1869		EMAIL Aletab@shaw.ca	

REASON FOR TODAY'S CALL:  
Garburator jammed

DESCRIPTION OF WORK PERFORMED:

I was able to unjam the garburator and tested by filling and draining the sink while running the garburator. Nothing out of the ordinary was pulled out of the garburator, it appeared to be seized up due to rust buildup. I informed Aleta that it would be a good idea to make sure the garburator is run periodically to help mitigate the chances of rust building up to the point where it seizes up again.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00
			SUBTOTAL:	\$109.00
			GST (5%):	\$5.45
			TOTAL:	\$114.45

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2017-09-19

CUSTOMER SIGNATURE

DATE