

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2017-09-22	TECHNICIAN Darren Mann		JOB/O 7731	RDER #	REFERENCE TEXT Client reference
FIRST NAME Heather		LAST NAME Beattie	7		
BILLING ADDRESS COMPANY / BILLING NAME 1501 - 1280 RICHARDS ST VANCOUVER, V6B1S2 BRITISH COLUMBIA, CANADA		\sim	4	SERVICE ADDRESS 1501 - 1280 RICHARDS ST BUZZER: 00741 VANCOUVER, V6B1S2 BRITISH COLUMBIA, CANADA	
PHONE 1.403.797.0068				EMAIL heatherabeattie@gmail.com	

REASON FOR TODAY'S CALL:

The kitchen sink on right side where our garbourator is located is leaking underneath.

DESCRIPTION OF WORK PERFORMED:

The garburator was leaking through cracks in the housing. I replaced the garburator with a new Badger5 and tested by filling and draining the sink while running the garburator.

QTY.	CODE		DESCRIPTION		PRICE
1	1 Supply & Install 1/2HP Badger5 Garburator				\$319.00
Gwe us Feedback			WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$319.00
Please visit our feedback page at:			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$15.95
	www.yaletownplumbing.com/feedback [1] Fill in the required details from your		WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$334.95
invoice and tell us how we did. <u>Thank You!</u>			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAG RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		
			CUSTOMER SIGNATURE DATE		