

🕒 @SimplyPlumbing 🛛 🚹 YaletownPlumbing

HST #837181627

DATE	TECHNICIAN		JOB/ORDER #		REFERENCE TEXT	
2017-09-27	Darren Mann		7753		Client reference	
FIRST NAME Albert		LAST NAME Yeo	7			
BILLING ADDRESS COMPANY / BILLING NAME 2309 - 108 WEST CORDOVA ST VANCOUVER, V6B 0G6 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 2309 - 108 WEST CORDOVA ST, BUZZER 2117 VANCOUVER, V6B 0G6 BRITISH COLUMBIA, CANADA		
PHONE				EMAIL		
604.428.6034				stimmgabel@gmail.com		

REASON FOR TODAY'S CALL:

1. Noisy garburator. 2. Water tank fills without stopping in WC. Please let me know if the photos are not acceptable or are unclear to see.

DESCRIPTION OF WORK PERFORMED:

-I replaced the toilet FillValve with new and tested. -I was able to unjam the garburator by removing a screw. Tested by filling and draining the sink while running the garburator.

QTY.	CODE			DESCRIPTION	UNIT PRICE	PRICE	
1		Replace toilet FillValve - standard				\$159.00	\$159.00
Guve us Feedback Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your invoice and tell us how we did. <u>Thank Youl</u>		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY <u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS. THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY		SUBTOTAL:	\$159.00	
					GST (5%):	\$7.95	
				TOTAL:	\$166.95		
		MATERIALS L SETTLED, RU RESULTING F	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RI STED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUT FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MA . & O. E.				
				CUSTOMER SIGNATURE	DATE		