

(B) @SimplyPlumbing | YaletownPlumbing

DATE

HST #837181627

DATE 2017-09-26	TECHNICIAN Darren Mann		JOB/ORDER # 7755		REFERENCE TEXT 17-1225	
FIRST NAME Advent		LAST NAME Admin				
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA		9	4	SERVICE ADDRESS 205 - 1068 WEST BROADWAY LIA: 778.227.8609 VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.736.6478				EMAIL andrea@adventvancouver.com		

REASON FOR TODAY'S CALL:

Garburator jammed

DESCRIPTION OF WORK PERFORMED:

The garburator had deteriorated to the point that the motor detached from the grinding chamber. I replaced the garburator with a new Badger5 and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE			DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2	2HP Badger5	Garburator	\$319.00	\$319.00
Para est Goodle			WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	SUBTOTAL:	\$319.00
	Gwe us Feedback Please visit our feedback page at:				GST (5%):	\$15.95
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		INTEREST AT	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$334.95	
		MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.				
			2017-09-26			