

(E) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2017-10-02	TECHNICIAN Darren Mann		JOB/O 7778	RDER #	REFERENCE TEXT Client reference
FIRST NAME Sheilan		LAST NAME Dove	7		
BILLING ADDRESS COMPANY / BILLING NAME 603 - 1006 BEACH AVE VANCOUVER, V6E1T7 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 603 - 1006 BEACH AVE BUZZER: 603 VANCOUVER, V6E1T7 BRITISH COLUMBIA, CANADA	
PHONE 604.685.1995				EMAIL sheilan.d@hotmail.com	

REASON FOR TODAY'S CALL:

Removal of the garburator. Check on running toilet.

## DESCRIPTION OF WORK PERFORMED:

-I removed the garburator, installed a basket strainer in it?s place and repiped the ABS drainage. Tested by filling and draining both sides of the sink multiple times. -I took a look at the toilet and tested by flushing multiple times. A new fillvalve and flapper will have to be ordered from a Kohler.

QTY. CODE		DESCRIPTION	UNIT PRICE	PRICE
1 Delete Garbura	tor & Re-Pipe A	\$219.00	\$219.00	
Current Goodles	WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$219.00
<b>Give us Feedbac</b> Please visit our feedback page at:	ĸ	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$10.95
www.yaletownplumbing.com/feedback [ Fill in the required details from your		WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$229.95
invoice and tell us how we did.	MATERIALS SETTLED, R RESULTING <u>TERMS</u> : NET CHARGES, E	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BORKEN, USTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK E. & O. E.		