



2017-10-05

DATE

HST #837181627

DATE 2017-10-05	TECHNICIAN Darren Mann		JOB/O 7762	RDER #	REFERENCE TEXT Client reference
FIRST NAME Dunowen Properties		LAST NAME Admin	97		
BILLING ADDRESS DUNOWEN PROPERTIES 201 - 1288 ALBERNI STREET VANCOUVER, V6E 4N5 BRITISH COLUMBIA, CANADA	4			SERVICE ADDRESS 1801 - 1288 ALBERNI ST VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.736.1900				EMAIL operations@dunowen.com	

REASON FOR TODAY'S CALL: Garburator housing cracked.

DESCRIPTION OF WORK PERFORMED:

I replaced the garburator with a new Badger5 and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	17	Supply & Install 1/2HP Badger5 Garburator	\$319.00	\$319.00
<i>Q</i>	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$319.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$15.95
		s from your	TOTAL:	\$334.95
		MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,	S	

CUSTOMER SIGNATURE