

(B) @SimplyPlumbing | YaletownPlumbing



HST #837181627

DATE 2017-10-06	TECHNICIAN Darren Mann		JOB/ORDER # 7799		REFERENCE TEXT Client reference			
FIRST NAME Easyrent		LAST NAME Admin	97					
BILLING ADDRESS EASYRENT REAL ESTATE SERVICES LTD. 100 - 1290 HOMER ST VANCOUVER, V6B2Y5 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS  414 - 939 HOMER ST BUZ#0105 PAUL: 604.704.4130 VANCOUVER, BRITISH COLUMBIA, CANADA				
PHONE 604.662.3279				EMAIL info@easyrent.ca				

## REASON FOR TODAY'S CALL:

issue with shower knob \*refer to email thread

## DESCRIPTION OF WORK PERFORMED:

The cartridge within the shower valve was stripping internally and the Integral shut off valves were not functioning. I first repaired the Integral shut off valves by replacing the washers, stems, packing, and packing nuts. I then replaced the cartridge(Tempress ii) within the shower valve and tested.

QII.	CODE		DESCRIPTION	UNII PRICE	PRICE
1		Replace Shower Cartridge - Temp II		\$209.00	\$209.00
2	11	Integral Stop - Repair		\$25.00	\$50.00
Q	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		TY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$259.00
Please visit our feedback page at:			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	GST (5%):	\$12.95
	www.yaletownplumbing.com/feedback [1] Fill in the required details from your			TOTAL:	\$271.95

Thank You!

invoice and tell us how we did.

MADE THAT SERVICES LISTED MATERIALS LISTED HEREON A SETTLED, RUSTED, DETERIORA	ABOVE ARE SATISFACTORY COI RE CORRECT. YALETOWN PLUM	COUNTS. ACKNOWLEDGEMENT IS HEREBY MPLETED AND THAT CHARGES AND BING IS NOT RESPONSIBLE FOR BROKEN, IS, CLEAN OUTS AND ANY OTHER DAMAGES AND RIPINIG
		R LABOUR, MATERIALS AND TRUCK
CHARGES. E. & O. E.		
		2017-10-06
CII	STOMER SIGNATURE	DATE