



2017-10-11

DATE

HST #837181627

DATE 2017-10-11	TECHNICIAN Darren Mann		JOB/O 7814	RDER #	REFERENCE TEXT Client reference
FIRST NAME Mehmud		LAST NAME Karmali			
BILLING ADDRESS COMPANY / BILLING NAME 601 - 950 CAMBIE ST VANCOUVER, V6B 5X5 BRITISH COLUMBIA, CANADA		19	4	SERVICE ADDRESS  303 - 950 CAMBIE ST VANCOUVER, V6B 5X5 BRITISH COLUMBIA, CANADA	
PHONE 604-603-4332				EMAIL mehmud.karmali@gmail.com	

## REASON FOR TODAY'S CALL:

Replacement of an old Sinkmaster 550 garburator with a new Waste King 3300 EZ Mount garburator in a condo kitchen.

## DESCRIPTION OF WORK PERFORMED:

-l installed the customer supplied garburator and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE		UNIT PRICE	PRICE	
1		Install Customer Sup	ner Supplied Garburator - Waste King		\$149.00
Q	Gwe us Feedback  Veranty:  Veranty:		ARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$149.00
			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.45
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.  Thank Youl			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$156.45
		we did.	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE