



HST #837181627

DATE 2017-10-20	TECHNICIAN Darren Mann		JOB/ORDER # 7836		REFERENCE TEXT Client reference			
FIRST NAME Waltson		LAST NAME Liao	97					
BILLING ADDRESS COMPANY / BILLING NAME 408 - 522 MOBERLY RD VANCOUVER, V5Z4G4 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 408 - 522 MOBERLY RD BUZZER: 032 VANCOUVER, V5Z4G4 BRITISH COLUMBIA, CANADA				
PHONE 604.961.9642				EMAIL waltsonliao@gmail.com				

REASON FOR TODAY'S CALL:

Remove garburator and replace with basket strainer.

DESCRIPTION OF WORK PERFORMED:

I removed the garburator, installed a basket strainer in it?s place, and repiped the ABS drainage. Tested by filling and draining both sides of the sink multiple times. During testing I noticed the right side sink strainer was leaking. I replaced this strainer with new and tested again.

QTY.	CODE		UNIT PRICE	PRICE	
1		Delete Garburator & Re-Pipe A	\$219.00	\$219.00	
1		Kitchen Sink Strainer Assembly	\$35.00	\$35.00	
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		warranty:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$254.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$12.70
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$266.70

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

raplian

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2017-10-20

CUSTOMER SIGNATURE

DATE