

HST #837181627

DATE 2017-10-20	TECHNICIAN Darren Mann		JOB/ORDER # 7843	REFERENCE TEXT Client reference
FIRST NAME		LAST NAME		
Giselle		Lam		
BILLING ADDRESS COMPANY / BILLING NAME 509 - 111 WEST GEORGIA ST VANCOUVER, V6B1T8 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 509 - 111 WEST GEORGIA ST NO BUZ VANCOUVER, V6B1T8 BRITISH COLUMBIA, CANADA	
PHONE		EMAIL	EMAIL	
604.719.8307		Gisellelam@hotmail.c	Gisellelam@hotmail.com	

REASON FOR TODAY'S CALL:

There is little water coming out from the cold water faucet in the bathroom. Hot water is fine. Cold and hot water in the kitchen are fine. I tried turning on and off of the valve and it didn't make a difference.

DESCRIPTION OF WORK PERFORMED:

The cold shut off valve under the sink failed, I repaired this valve by replacing the washer, stem, packing, packing nut, and handle. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Repair 1/2" x 3/8" Angle or Straight Stop	\$139.00	\$139.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$139.00
		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$6.95
			TOTAL:	\$145.95
		WE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROK SETTLED BUSTED DETERIORATION OF LEAD PIPES FIXTURES OF AN OUTS AND ANY OTHER DAM.	EN,	

CUSTOMER SIGNATURE

DATE