



HST #837181627

DATE 2017-10-25	TECHNICIAN Darren Mann		JOB/ORDER # 7849	REFERENCE TEXT Client reference
FIRST NAME De Jersey		LAST NAME Don		
BILLING ADDRESS COMPANY / BILLING NAME 2102 - 1500 HORNBY ST. VANCOUVER, V6Z 2R1 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS  2102 - 1500 HORNBY ST. BUZZER: 3073 VANCOUVER, V6Z 2R1 BRITISH COLUMBIA, CANADA	
PHONE 604-417-8509			EMAIL dwdejersey@gmail.cor	n

## REASON FOR TODAY'S CALL:

On your last visit you looked at our Kohler toilet which 'runs' constantly and you advised that the problem was that the toilet had a non-Kohler fill valve installed and that this was likely causing the running problem. I would like to have a Kohler fill valve installed to hopefully stop the running.

## DESCRIPTION OF WORK PERFORMED:

I installed the Kohler 84499 conversion kit and tested. I did not install the new flapper(left new one with De Jersey) because the existing one was in good shape.

QTY.	CODE	DESCRIPTION			PRICE
1		Replace Fill-Valve F	Flapper Supply - Kohler 84499	\$299.00	\$299.00
Q.,,,,	(1	and a de	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$299.00
	Gwe us Feedback  lease visit our feedback page at:		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$14.9
Fill in the required details from your invoice and tell us how we did.  Thank You!			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$313.9
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

DATE