



DATE 2017-10-26	TECHNICIAN Darren Mann	JOB/ORDER # 7845	REFERENCE TEXT Client reference
FIRST NAME Mileva		LAST NAME Ponorac	
BILLING ADDRESS COMPANY / BILLING NAME 902 - 1010 RICHARDS ST VANCOUVER, V6B 1G2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 902 - 1010 RICHARDS ST VANCOUVER, V6B 1G2 BRITISH COLUMBIA, CANADA	
PHONE 778-990-3672		EMAIL mponorac@gmail.com	

REASON FOR TODAY'S CALL:  
1. Replace Badger5 Garburator.

DESCRIPTION OF WORK PERFORMED:  
-The garburator had cracks in the housing. I replaced the garburator with a new Badger5 and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Badger5 Garburator	\$319.00	\$319.00

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

*Darren Mann*  
*Mileva Ponorac*

2017-10-26

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$319.00
GST (5%):	\$15.95
TOTAL:	\$334.95