



2017-11-14

DATE

HST #837181627

DATE 2017-11-14	TECHNICIAN Darren Mann		JOB/O 7925	RDER #	REFERENCE TEXT
FIRST NAME Dunowen Properties		LAST NAME Admin			
BILLING ADDRESS DUNOWEN PROPERTIES 201 - 1288 ALBERNI STREET VANCOUVER, V6E 4N5 BRITISH COLUMBIA, CANADA		19	4	SERVICE ADDRESS 405 - 1200 ALBERNI ST VANCOUVER, BRITISH COLUMBIA, CANADA	N
PHONE 604.736.1900				EMAIL operations@dunowen.com	

REASON FOR TODAY'S CALL:

Issues with garburator.

DESCRIPTION OF WORK PERFORMED:

The garburator grinding chamber had deteriorated to the point that bits of metal were flaking off. I replaced the garburator with new and tested by filling and draining

QTY.	CODE		DESCRIPTION			
1		Supply & Install 1/2HF	\$279.00	\$279.00		
Gwe us Feedback WARRAN			IRRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$279.00	
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		ck page at:	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	GST (5%):	\$13.95	
		ls from your	NTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$292.95	
		we did.	MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. FERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.			

CUSTOMER SIGNATURE