

HST #837181627

DATE 2017-11-29	TECHNICIAN Darren Mann		JOB/ORDER # 7969		REFERENCE TEXT Client reference
FIRST NAME Jun		LAST NAME Zhou			
BILLING ADDRESS COMPANY / BILLING NAME 302 - 1068 WEST BROADWAY VANCOUVER , V6H 0A7 BRITISH COLUMBIA, CANADA		9	4	SERVICE ADDRESS 302 - 1068 WEST BROADWAY VANCOUVER , V6H 0A7 BRITISH COLUMBIA, CANADA	
PHONE 604.266.7433				EMAIL Jun_zhou_ca@yahoo.com	

REASON FOR TODAY'S CALL:

Dripping (leaking) from disposal of kitchen sink

DESCRIPTION OF WORK PERFORMED:

-The garburator was leaking through the bottom and could not be repaired. I replaced the garburator with a new Badger5 and tested by filling and draining the sink multiple times while running the garburator. -The Toilet Tank Lever was broken, causing the chain to get stuck below the flapper and the toilet to run. I replaced the

QIY.	CODE		UNIT PRICE	PRICE	
1		Supply & Install 1/2HP Badger5 Garburator			\$319.00
1		Replace Tank Lever -Standard		\$20.00	\$20.00
		PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$339.00	
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$16.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$355.95

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES. E. & O. E.

2017-11-29

CUSTOMER SIGNATURE

DATE