

Phone: 604.727.4484 yaletownplumbing.com

HST #837181627

| DATE 2017-11-30 | TECHNICIAN Darren Mann | | JOB/ORDER # 7974 | REFERENCE TEXT Client reference | | |
|---|---------------------------|--------------------|-------------------------------------|---|--|--|
| FIRST NAME Avril | | LAST NAME Brett | | | | |
| BILLING ADDRESS COMPANY / BILLING NAME 189 KEEFER STREET VANCOUVER, V6A0C8 BRITISH COLUMBIA, CANADA | | | #905 - 189 KEEFEF VANCOUVER, V6A | SERVICE ADDRESS #905 - 189 KEEFER STREET, BUZZER 9057 VANCOUVER, V6A0C8 BRITISH COLUMBIA, CANADA | | |
| PHONE 7788285903 | | | EMAIL avrilbrett@gmail.com | m | | |

REASON FOR TODAY'S CALL:

Hi there, we live in a condo building (2.5 years old) and have been experiencing a sewer-type smell coming from the toilet area. I've plugged and blocked off the shower drain and sink drains and overflows and the problem persists so I'm fairly sure it's coming from the toilet. The toilet appears to flush smoothly and the area surrounding the toilet is very clean. The toilet is sealed to the tile all around except on the back side where it sits about 2 inches from the wall. I've also tried creating a seal on the back wall side with a damp towel to see if this would help but so far there has been no improvement. Putting deodorizer into the toilet bowl briefly covers up the smell. Thank you so much for your help! Avril

DESCRIPTION OF WORK PERFORMED:

I lifted the toilet and found the wax seal to be breached. I reinstalled the toilet with a new wax seal and supply line. Tested by flushing a dozen times while using a camera around the back to inspect for leaks between the tank & bowl, and the toilet & floor. Toilet is flushing normally with no signs of leaking.

| QTY. | CODE | DESCRIPTION | UNIT PRICE | PRICE |
|---|---------------|---|------------|----------|
| 1 | | Replace Toilet Wax Seal - Standard | | \$189.00 |
| <i>Q.</i> | SUBTOTAL: | \$189.00 | | |
| Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your | | LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF | GST (5%): | \$9.45 |
| | | | TOTAL: | \$198.45 |
| | tell us how v | MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, | | |
| | | CUSTOMER SIGNATURE DATE | | |