

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2017-12-18	TECHNICIAN Darren Mann		JOB/ORDER # 8027	REFERENCE TEXT Client reference
FIRST NAME Richard		LAST NAME Nilsson		
BILLING ADDRESS COMPANY / BILLING NAME 707 - 1010 RICHARDS ST VANCOUVER, V6B1G2 BRITISH COLUMBIA, CANADA			SERVICE ADDRI 707 - 1010 RICH BUZZER: 1818 VANCOUVER, VI BRITISH COLUM	ARDS STREET 5B1G2
PHONE 604.700.6402	~		EMAIL jrnilsson@yahoo.	com

REASON FOR TODAY'S CALL:

replace garberator with regular drain pipes.

DESCRIPTION OF WORK PERFORMED:

I removed the garburator, installed a basket strainer in it?s place, and repiped the ABS drainage. Tested by filling and draining both sides of the sink multiple times.

QTY.	CODE	DESCRIPTION				ICE	PRICE
1		Delete Garburator & Re-Pipe ABS Drainage			\$21	9.00	\$219.00
0		and a du	WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTO	ΓAL:	\$219.00
Gwe us Feedback Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your		<u>L</u>	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTI	GST (5%	6):	\$10.95	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:		\$229.95	
	t tell us how v		MATERIALS I SETTLED, RU RESULTING I	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AN LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR B JSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER I FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUC . & O. E. CUSTOMER SIGNATURE DATE	ROKEN, MAMAGES		