

HST #837181627

DATE 2017-12-21	TECHNICIAN Darren Mann		JOB/ORDER # 8028	REFERENCE TEXT Client reference	
FIRST NAME John		LAST NAME Fukushima		·	
BILLING ADDRESS COMPANY / BILLING NAME 406 - 518 BEATTY ST VANCOUVER, V6B6G8 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 406 - 518 BEATTY ST, BUZZER 026 VANCOUVER, V6B6G8 BRITISH COLUMBIA, CANADA		
PHONE 604.809.1814			EMAIL the.fook@gmail.com	=	

REASON FOR TODAY'S CALL:

Hello - Shower output recently developed low pressure. Removed the shower head unit but pressure right out of wall is also low. Pressure out of main tub taps is fine, perhaps a faulty or clogged cartridge? This is for a single handle Moen fixture. (See attached photo) Cheers

DESCRIPTION OF WORK PERFORMED:

QTY.	CODE	DESCRIPTION			PRICE
1		Labour		\$109.00	\$109.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$109.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$114.45
		we did.	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

2017-12-21

DATE