



DATE 2017-12-21	TECHNICIAN Darren Mann	JOB/ORDER # 8041	REFERENCE TEXT Client reference
FIRST NAME Mark		LAST NAME Tucker	
BILLING ADDRESS COMPANY / BILLING NAME 1205 - 1050 SMITHE ST. VANCOUVER, V6E 4T4 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1205 - 1050 SMITHE ST., BUZZER 3360 VANCOUVER, V6E 4T4 BRITISH COLUMBIA, CANADA	
PHONE 778.997.9659		EMAIL mptucker@gmail.com	

REASON FOR TODAY'S CALL:
 Small Leak on pipe leading to Garburator under Kitchen Sink. Upper pip in image at junction.


DESCRIPTION OF WORK PERFORMED:
 The dishwasher drain coupling was cracked. I replaced this drain coupling and tested by running the garburator through a few fill and drain cycles.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace DW Drain Coupling	\$129.00	\$129.00
SUBTOTAL:				\$129.00
GST (5%):				\$6.45
TOTAL:				\$135.45

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.


 _____ 2017-12-21
 CUSTOMER SIGNATURE DATE