



HST #837181627

DATE 2018-01-04	TECHNICIAN Darren Mann		JOB/ORDER # 8050	REFERENCE TEXT Client reference	
FIRST NAME Bill		LAST NAME Crowley		·	
BILLING ADDRESS COMPANY / BILLING NAME 2602 - 1255 SEYMOUR ST BUZ#960 VANCOUVER, V6B0H1 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 2602 - 1255 SEYMOUR ST BUZ#960 BUZZER: 960 VANCOUVER, V6B0H1 BRITISH COLUMBIA, CANADA		
PHONE 604.720.1970			EMAIL bilcrow@yahoo.com		

REASON FOR TODAY'S CALL:

garburator is not working. Might be something jammed or it could need to be replaced.

DESCRIPTION OF WORK PERFORMED:

The garburator was the original to the building and had cracks in the housing. I replaced the garburator with a new Badger5 and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION			PRICE			
1		Supply & Install 1/2HP Badger5 Garburator			\$319.00			
<i>Q.</i>	(1	eedback warranty: PARTS - SUBJECT TO MANUFAC	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY					
	t our feedbac	LABOUR - 1 YEAR ON NEW UNIT	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO		\$15.95			
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY		\$334.95			
		MADE THAT SERVICES LISTED ABOVE ARE SATI	MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK					

CUSTOMER SIGNATURE

DATE