



DATE 2018-01-04	TECHNICIAN Darren Mann	JOB/ORDER # 8062	REFERENCE TEXT Client reference
FIRST NAME Sophia		LAST NAME Lee	
BILLING ADDRESS COMPANY / BILLING NAME 270 E 2ND AVE VANCOUVER, V5T 1B7 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 270 E 2ND AVE VANCOUVER, V5T 1B7 BRITISH COLUMBIA, CANADA	
PHONE 604.362.3971		EMAIL sophiajelee@gmail.com	

REASON FOR TODAY'S CALL:
Our garberator is leaking water from the bottom of the unit.

DESCRIPTION OF WORK PERFORMED:
The garburator was the original to the building and had cracks in the housing. I replaced the garburator with a new Badger5 and tested by filling and draining the sink multiple times while running the garburator.


QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Badger5 Garburator	\$319.00	\$319.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

 <hr/> CUSTOMER SIGNATURE	2018-01-04 <hr/> DATE
---	--------------------------

SUBTOTAL:	\$319.00
GST (5%):	\$15.95
TOTAL:	\$334.95