



HST #837181627

DATE 2018-01-05	TECHNICIAN Darren Mann		JOB/ORDER # 8059	REFERENCE TEXT Client reference	
FIRST NAME Katherine		LAST NAME Frost			
BILLING ADDRESS COMPANY / BILLING NAME 308 - 2885 SPRUCE ST VANCOUVER, V6H 2R4 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS  308 - 2885 SPRUCE ST CHRIS(HUSBAND): 604.730.0245(H) OR 604.785.9851(M) BUZZER: 62 VANCOUVER, V6H 2R4 BRITISH COLUMBIA, CANADA		
PHONE 604.730.0245			EMAIL kjfrost@telus.net		

## REASON FOR TODAY'S CALL:

The piping leading from the in-sink disposal is broken where it meets the pipe coming from the sink.

## DESCRIPTION OF WORK PERFORMED:

The ABS drainage dropped down and detached from the garburator drain 90. I raised the drainage back up, replaced a warm slipjoint beveled washer at the drain 90 connection, and used metal strapping to secure the drainage as high as it will go to mitigate the chances of this happening again.

QTY.	CODE		UNIT PRICE	PRICE	
1	<i>I</i> .	Labour		\$109.00	\$109.00
<i>Q.</i>	Gwe us Feedback  Please visit our feedback page at:		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$109.00
			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.45
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.  Thank You!		.com/feedback [1]	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$114.45
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETILED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		
			2018-01-05		