

HST #837181627

DATE 2018-01-10	TECHNICIAN Darren Mann		JOB/ORDER # 8064	REFERENCE TEXT Client reference	
FIRST NAME Vanessa		LAST NAME Do			
BILLING ADDRESS COMPANY / BILLING NAME 1008 - 888 HOMER ST VANCOUVER, V6B0H7 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 1008 - 888 HOMER STREET BUZZER: 0300 VANCOUVER, V6B0H7 BRITISH COLUMBIA, CANADA		
PHONE 604.341.6146			EMAIL vanessado@hotmail.c	EMAIL vanessado@hotmail.com	

REASON FOR TODAY'S CALL:

In sink garbage disposal is leaking and unable to turn on wall switch to run the garbage disposal.

CHARGES. E. & O. E.

DESCRIPTION OF WORK PERFORMED:

The garburator was leaking from cracks in the housing and could not be repaired. I replaced the garburator with a new Badger5 and tested by filling and draining the sink while running the garburator.

QTY.	CODE	DESCRIPTION			PRICE
1		Supply & Install 1/2HP Badger5 Garburator		\$319.00	\$319.00
<i>Q</i>			WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$319.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback Fill in the required details from your invoice and tell us how we did. Thank You!			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$15.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$334.95
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREDA ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES, E. & O. E.		

CUSTOMER SIGNATURE

DATE