

HST #837181627

DATE 2018-01-10	TECHNICIAN Darren Mann		JOB/ORDER # 8076	REFERENCE TEXT Client reference	
FIRST NAME Saira		LAST NAME Devji			
BILLING ADDRESS COMPANY / BILLING NAME 3503 - 1408 STRATHMORE MEWS VANCOUVER, V6Z 3A9 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS  3503 - 1408 STRATHMORE MEWS, BUZZER #1229 VANCOUVER, V6Z 3A9 BRITISH COLUMBIA, CANADA		
PHONE 604.721.7363			EMAIL Sdevji@hotmail.com	EMAIL Sdevji@hotmail.com	

REASON FOR TODAY'S CALL: bathtub draining slowly.

## **DESCRIPTION OF WORK PERFORMED:**

I used the PowerSpin drain snake to clear hair, elastics, and a plastic razor cap from the tub drain. I also cleared hair out of the lav sink drain.

QTY.	CODE	DESCRIPTION			PRICE
1		Clean drain using PowerSpin / Tub/Shower			\$139.00
		and a all w	ARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$139.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$145.95
			INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND		

<u> Thank You!</u>

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES, E. & O. E.

