



DATE 2018-01-12	TECHNICIAN Darren Mann	JOB/ORDER # 8098	REFERENCE TEXT Client reference
FIRST NAME Ross		LAST NAME Nelson	
BILLING ADDRESS COMPANY / BILLING NAME 111 - 1975 PENDRELL ST VANCOUVER, V6G1T6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 111 - 1975 PENDRELL ST, BUZZER 111 VANCOUVER, V6G1T6 BRITISH COLUMBIA, CANADA	
PHONE 604.688.7677		EMAIL tucker23@shaw.ca	

REASON FOR TODAY'S CALL:
 Repair shut off valve under lavatory sink.

DESCRIPTION OF WORK PERFORMED:
 I repaired the Hot & Cold shut off valves under the lavatory sink (connected to the faucet) by replacing the washers, stems, packing, packing nuts, and handles. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Repair 1/2" x 3/8" Angle or Straight Stop	\$139.00	\$139.00
1		Repair 1/2" x 3/8" Angle or Straight Stop - ADD-ON	\$25.00	\$25.00
SUBTOTAL:			\$164.00	\$164.00
GST (5%):			\$8.20	\$8.20
TOTAL:			\$172.20	\$172.20

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



 CUSTOMER SIGNATURE

2018-01-12

 DATE