

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2018-01-17	TECHNICIAN Darren Mann		JOB/ORDER # 8096	REFERENCE TEXT Client reference	
FIRST NAME Joe		LAST NAME DeJesus		·	
BILLING ADDRESS COMPANY / BILLING NAME 2604 - 1155 SEYMOUR ST. VANCOUVER , V6B 1K2 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 2604 - 1155 SEYMOUR ST. HUGO(TENANT): 778.319.0470 BUZ#416 VANCOUVER , V6B 1K2 BRITISH COLUMBIA, CANADA		
PHONE 604-329-6087			EMAIL valmel@shaw.ca		

REASON FOR TODAY'S CALL: Instant hot water tank fitting leaking

DESCRIPTION OF WORK PERFORMED:

The leak was coming from the press fitting on top of the instant hot water unit. The copper that pushes into it was rough, likely from someone using pliers on it. I disconnected the copper, used sand cloth to smooth it out, and reinstalled. The leaking has stopped and there were no other signs of leaking from the unit or it?s connections.

QTY.	CODE	DESCRIPTION			PRICE
1		Labour		\$109.00	\$109.00
Give us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		and hack	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$109.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$114.45
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. <u>TERMS</u> : NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. 2018-01-17		
			CUSTOMER SIGNATURE DATE		