

HST #837181627

DATE 2018-01-22	TECHNICIAN Darren Mann		JOB/ORDER # 8136	REFERENCE TEXT Client reference	
FIRST NAME Michelle		LAST NAME Laurent		·	
BILLING ADDRESS COMPANY / BILLING NAME 208 - 1783 MANITOBA ST VANCOUVER, V5Y0K1 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 208 - 1783 MANITOB BUZ#LAURENTM VANCOUVER, V5Y0I BRITISH COLUMBIA	A STREET	
PHONE 604.704.4082		EMAIL michellelaurent1998@	EMAIL michellelaurent1998@gmail.com		

REASON FOR TODAY'S CALL:

The kitchen sink seems clogged, water can?t flow. The grinder under the sink also makes a weird sound.

CHARGES. E. & O. E.

DESCRIPTION OF WORK PERFORMED:

The garburator was not draining due to onion skins being stuck in the drain 90. The garburator was leaking through the bottom and could not be repaired. I replaced the garburator with a new Badger5 and tested by filling the sink 6? and draining multiple times while running the garburator.

TECHNICIAN RECOMMENDATIONS:

The wood glued to the underside of the kitchen counter that the metal strapping that secures the sink attaches to fell off. I suggest using metal L-brackets to help secure the sink.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Badger5 Garburator		\$319.00
0	(1	eedback warranty: Parts - Subject to Manufacturer's Warranty	SUBTOTAL:	\$319.00
	t our feedbac	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$15.95
	ownplumbing. equired detail	warranty on customer supplied materials. s from your Interest at the legal rate is charged on past due accounts, acknowledgement is hereby	TOTAL:	\$334.95
invoice and tell us how we did.				

Thank You!

raweit

CUSTOMER SIGNATURE

RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

DATE