



DATE 2018-01-23	TECHNICIAN Darren Mann	JOB/ORDER # 8140	REFERENCE TEXT
FIRST NAME Dennis		LAST NAME Enomoto	
BILLING ADDRESS 1506 - 1050 SMITHE ST VANCOUVER, V6E 4T4 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1506 - 1050 SMITHE ST CRAIG(TENANT): 604.512.1867 BUZ#4010 VANCOUVER, V6E 4T4 BRITISH COLUMBIA, CANADA	
PHONE 604-623-3387		EMAIL dyenomoto@gmail.com	

REASON FOR TODAY'S CALL:
Garburator stopped working. May need to be replaced.

DESCRIPTION OF WORK PERFORMED:
The garburator grinding chamber was deteriorated to the point that bits of metal were flaking off. I replaced the garburator with a new Waste King 1001 and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$279.00
GST (5%):	\$13.95
TOTAL:	\$292.95

_____ 2018-01-23
 CUSTOMER SIGNATURE DATE