

2018-01-23

DATE

HST #837181627

DATE 2018-01-23	TECHNICIAN Darren Mann		JOB/ORDER # 8113	REFERENCE TEXT 18-0075	1
FIRST NAME Advent		LAST NAME Admin			
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 1205 - 822 HOMER S' AMIN: 778.892.6060 NATASHA: 778.709.09 VANCOUVER, BRITISH COLUMBIA,	907	
PHONE 604.736.6478			EMAIL andrea@adventvanco	EMAIL andrea@adventvancouver.com	

REASON FOR TODAY'S CALL:

Ensuite bathroom: -Sink stopper detached. -Towel rack loose.

DESCRIPTION OF WORK PERFORMED:

-The mechanical Lav drain assembly was cracked and could not be repaired. I replaced the mechanical drain assembly and tested by filling and draining the sink multiple times. -Unfortunately one of the drywall inserts used to secure the hand towel rack popped out of the wall and I didn?t have any replacements that would work.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	7)	Replace Lav Drain - Mechanical		\$159.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback Fill in the required details from your invoice and tell us how we did. Interest at the legal rate is charged on past due. Made that services listed above are satisfactory materials listed hereon are correct, yaletown plusted. Resulting from cleaning or repairing existing fixt		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$159.00
		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$7.95
			TOTAL:	\$166.95
		MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK		

CUSTOMER SIGNATURE