



HST #837181627

DATE 2018-01-25	TECHNICIAN Darren Mann		JOB/ORDER # 8130	REFERENCE TEXT Client reference	
FIRST NAME Alan and Jola		LAST NAME Berkman			
BILLING ADDRESS COMPANY / BILLING NAME 304 - 1066 HAMILTON ST VANCOUVER , V6B 2R9 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 304 - 1066 HAMILTO JOLA BERKMAN(WIF VANCOUVER, V6B 2 BRITISH COLUMBIA	N ST FE): 1-250-667-1837 2R9	
PHONE 1-250-667-1837			EMAIL aberkman1@me.com	EMAIL aberkman1@me.com	

REASON FOR TODAY'S CALL:

Garburator has ceased to work. Doesn?t switch on at all and starting to smell.

DESCRIPTION OF WORK PERFORMED:

I was able to unjam the garburator by removing a penny that was lodged inside the grinding chamber. Tested by filling and draining the sink multiple times while

QTY.	CODE	DESCRIPTION			PRICE
1	/	Labour		\$109.00	\$109.00
Q.,,,		and and w	ARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$109.00
	Gwe us Feedback Please visit our feedback page at:		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.45
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$114.45
		we did.	MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

DATE