





2018-02-01

DATE

HST #837181627

DATE 2018-02-01	TECHNICIAN Darren Mann		JOB/ORDER # 8173	REFERENCE TEXT Client reference
FIRST NAME Susan		LAST NAME Morris-McEwan		
BILLING ADDRESS COMPANY / BILLING NAME 301 - 120 MILROSS AVE VANCOUVER, V6A 4K7 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 301 - 120 MILROSS A BUZ#1301 VANCOUVER, V6A 4I BRITISH COLUMBIA,	 <7
PHONE 778.918.3362		EMAIL susanmcewan@shaw	EMAIL susanmcewan@shaw.ca	

REASON FOR TODAY'S CALL:

There was a leak from the garburator, but now it is not working at all, I suspect it is plugged. Also dishwasher not draining, not sure if it is all connected.

DESCRIPTION OF WORK PERFORMED:

QTY.	CODE		DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Badger5 Garburator			\$319.00
e _m	(1	eedlack	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$319.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$15.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$334.95
		we did.	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES, E. & O. E.		

CUSTOMER SIGNATURE

CHARGES. E. & O. E.