



HST #837181627

DATE 2018-02-07	TECHNICIAN Darren Mann		JOB/ORDER # 8185		REFERENCE TEXT Client reference
FIRST NAME Jennifer		LAST NAME Chan			
BILLING ADDRESS COMPANY / BILLING NAME 2106 - 1295 RICHARDS ST VANCOUVER , V6B 1B7 BRITISH COLUMBIA, CANADA		4	4	SERVICE ADDRESS 2106 - 1295 RICHARDS ST BUZ#185 VANCOUVER , V6B 1B7 BRITISH COLUMBIA, CANADA	
PHONE 604-726-0837				EMAIL yiu.mun@gmail.com	

REASON FOR TODAY'S CALL:

Clogged bathtub

DESCRIPTION OF WORK PERFORMED:

I used the PowerSpin drain snake to clear hair from the tub drain and tested.

QTY.	CODE		UNIT PRICE	PRICE	
1		Clean drain using Powe	erSpin / Tub/Shower	\$139.00	\$139.00
Gwe us Feedback Please visit our feedback page at:			RRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$139.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.95
www.yaletownplumbing.com/feedback [1] Fill in the required details from your			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$145.95
invoice and tell us how we did.			ITEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY ADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND ATERIALS I ISTED HEREON ARE CORRECT VALETOWN BY LIMBURG IS NOT RESPONSIBLE FOR BROKEN.		_

Thank You!

SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2018-02-07

CUSTOMER SIGNATURE

DATE