



DATE 2018-02-13	TECHNICIAN Darren Mann	JOB/ORDER # 8181	REFERENCE TEXT Client reference
FIRST NAME Daniel		LAST NAME Max	
BILLING ADDRESS COMPANY / BILLING NAME 707 - 833 HOMER ST VANCOUVER, V6B 0H4 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 707 - 833 HOMER ST BUZ#1033 VANCOUVER, V6B 0H4 BRITISH COLUMBIA, CANADA	
PHONE 604.340.5961		EMAIL dingoxo@outlook.com	

REASON FOR TODAY'S CALL:
 Garburator is not working. No obvious damage or blockage from looking at the it through the sink whole. No sound either.

DESCRIPTION OF WORK PERFORMED:
 I was able to free up the garburator by removing a few pieces of rubber and a metal pin. Tested by filling and draining the sink multiple times while running th garburator.

TECHNICIAN RECOMMENDATIONS:
 I noticed a hairline crack starting to form in the garburator housing but there is no sign of leaking or seepage.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2018-02-13

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$109.00
GST (5%):	\$5.45
TOTAL:	\$114.45