



DATE 2018-02-09	TECHNICIAN Darren Mann	JOB/ORDER # 8202	REFERENCE TEXT 18-0219
FIRST NAME Advent		LAST NAME Admin	
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2403 - 1211 MELVILLE ST, BUZ ANNE MARIE: 778.233.9516 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.736.6478		EMAIL andrea@adventvancouver.com	

REASON FOR TODAY'S CALL:
Garburator broken

DESCRIPTION OF WORK PERFORMED:
The garburator was broken internally and could not be repaired. I replaced the garburator with new and tested by filling and draining both sides of the sink multiple times. The P-trap Union was loose, allowing a small amount of water to seep out. I tightened this union and tested again. No other leaks detected.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$279.00
GST (5%):	\$13.95
TOTAL:	\$292.95

_____ 2018-02-09

 CUSTOMER SIGNATURE DATE