

(E) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2017-12-22	TECHNICIAN Darren Mann		JOB/ORDER # 8048		REFERENCE TEXT Client reference
FIRST NAME Julia		LAST NAME Kim	7		
BILLING ADDRESS COMPANY / BILLING NAME 301 - 3421 CURLE AVE BURNABY, V5G 4P4 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 512 - 888 HOMER ST PATRICIA: 778.867.7284 BURNABY, BRITISH COLUMBIA, CANADA	
PHONE 604.418.1060				EMAIL julia786@yahoo.ca	

REASON FOR TODAY'S CALL: small leak under kitchen sink

DESCRIPTION OF WORK PERFORMED:

?Dec22: The majority of the leak was coming from the connection between the kitchen faucet spray head and hose. I tightened this connection and noticed the metal sheathing protecting the rubber tubing within the spray hose was broken. It is not leaking now but I will have to replace this as it will eventually start to leak. There was also a loose connection on the drainage below the sink which I tightened. ?Feb14: I Returned with the new Grohe spray hose, installed and tested.

QTY .	CODE		UNIT PRICE	PRICE	
1.5	1.	Discount Labour		\$99.00	\$148.50
1		Grohe Kitchen Faucet Spray	\$50.00	\$50.00	
0		WARRANT	7: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$198.50
Give us Feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$9.93
		.com/feedback [1]			\$208.43
		MATERIA SETTLED RESULTI TERMS:	IAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LIS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, N, RUSTED, DETERIORATION, OR LEAD PIPES, FLYTURES, CLEAN OUTS AND ANY OTHER DAMAGES NG FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK S. E. & O. E. 2017-12-22		
		-	CUSTOMER SIGNATURE DATE		