



DATE 2018-02-22	TECHNICIAN Darren Mann	JOB/ORDER # 8225	REFERENCE TEXT Client reference
FIRST NAME John		LAST NAME Wang	
BILLING ADDRESS COMPANY / BILLING NAME 1907 - 188 KEEFER PL VANCOUVER, V6B0J1 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1907 - 188 KEEFER PLACE BUZZER: #7110 VANCOUVER, V6B0J1 BRITISH COLUMBIA, CANADA	
PHONE 604.346.6686		EMAIL junwang.ubc@gmail.com	

REASON FOR TODAY'S CALL:
 Leaking garbage disposal. I included picture of the unit showing the model #; sorry I could not get a photo showing the leak though.

DESCRIPTION OF WORK PERFORMED:
 The garburator mounting bracket was loose and leaking. I tightened this mounting bracket and tested by filling and draining the sink while running the garburator. While there is no leaking and the garburator is functioning, the garburator grinding chamber is beginning to deteriorate and will likely have to be replaced in the not too distant future.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00
			SUBTOTAL:	\$109.00
			GST (5%):	\$5.45
			TOTAL:	\$114.45

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2018-02-22

CUSTOMER SIGNATURE

DATE