

HST #837181627

DATE 2018-02-23	TECHNICIAN Darren Mann		JOB/ORDER # 8227	REFERENCE TEXT Client reference	
FIRST NAME Tony		LAST NAME Yang			
BILLING ADDRESS COMPANY / BILLING 1463 WEST HASTING VANCOUVER, V6G3J BRITISH COLUMBIA,	S ST 9		SERVICE ADDRESS 1463 WEST HASTING VANCOUVER, V6G3J BRITISH COLUMBIA,	9	
PHONE 604.836.4637			EMAIL tsy2009@gmail.com		

REASON FOR TODAY'S CALL:

Require garbage disposal repair or replacement (there is a metal piece that has fallen off).

DESCRIPTION OF WORK PERFORMED:

I replaced the garburator with a new Waste King 1001 and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION			PRICE
1	7	Supply & Install 1/2HP Waste King 1001 Garburator			\$279.00
Q	, (I	eedback	TY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$279.00
	it our feedbac		<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$13.95
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY		\$292.95
		ve did. MATER SETTLE RESUL TERMS	MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

2018-02-23

DATE