



DATE 2018-03-02	TECHNICIAN Darren Mann	JOB/ORDER # 8247	REFERENCE TEXT Client reference
FIRST NAME Kyung Nam (Kay)		LAST NAME Ma	
BILLING ADDRESS COMPANY / BILLING NAME 1116 - 610 GRANVILLE ST VANCOUVER, V6C 3T3 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1116 - 610 GRANVILLE STREET BUZZER: 5118 VANCOUVER, V6C 3T3 BRITISH COLUMBIA, CANADA	
PHONE 1.236.333.3992		EMAIL kaymkn@hotmail.com	

REASON FOR TODAY'S CALL:
 The washer in the head of the faucet seems loose, which causes the leak from the head when water is running. Pls see the photo.

DESCRIPTION OF WORK PERFORMED:
 -The kitchen faucet spray head is cracked and will have to be replaced. I've suggested calling Grohe to ask if a new head can be sent out under warranty. -I added silicone around the shower trim.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL: \$109.00
 GST (5%): \$5.45
 TOTAL: \$114.45

CUSTOMER SIGNATURE

2018-03-02

 DATE