

2018-03-12

HST #837181627

DATE 2018-03-12	TECHNICIAN Darren Mann		JOB/ORDER # 8156	REFERENCE TEXT Client reference	
FIRST NAME Douglas C		LAST NAME Williamson		·	
BILLING ADDRESS COMPANY / BILLING NAME 616 - 888 BEACH AVE VANCOUVER, V6Z2P9 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 616-888 BEACH AVENUE BUZ#5023 VANCOUVER, V6Z2P9 BRITISH COLUMBIA, CANADA		
PHONE 604.689.5448			EMAIL dougcw1930@gmail.cc	om	

REASON FOR TODAY'S CALL:

Kitchen faucet leaks slightly at the point where it swings from one side of the sink to the other after I have been away for a week or more. After a week of use the leaking stops. It is the original faucet (Kohler 1993 model) and I want it repaired not replaced.

DESCRIPTION OF WORK PERFORMED:

I contacted Kohler and ordered replacement parts for the kitchen faucet. When the parts arrived I made a trip to the apartment, removed the spout, and reinstalled

QTY. CODE				DESCRIPTION		
1	//,	Labour			\$129.00	\$129.00
<i>Q</i>	we us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				SUBTOTAL:	\$129.00
	ease visit our feedback page at: www.yaletownplumbing.com/feedback [1] Il in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.45
				WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$135.4
Thank You!		MADE THAT S MATERIALS LI SETTLED, RUS RESULTING FI	THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY ERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND ISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, STED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES ROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK & O. E.			