

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2018-03-29	TECHNICIAN Darren Mann		JOB/ORDER # 8323		REFERENCE TEXT Client reference
FIRST NAME Sharon		LAST NAME Westler	7		
BILLING ADDRESS COMPANY / BILLING NAME 806 - 1438 RICHARDS ST. VANCOUVER, V6Z3B8 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 806 - 1438 RICHARDS ST. BUZZER: 1055 VANCOUVER, V6Z3B8 BRITISH COLUMBIA, CANADA	
PHONE 604.209.4470				EMAIL Westler27@yahoo.ca	

REASON FOR TODAY'S CALL:

2 yrars old garburator stopped working

## DESCRIPTION OF WORK PERFORMED:

I unjammed the garburator by removing a string what appeared to be a nut or crustacean shell. Tested by filling and draining the sink while running the garburator.

<b>QTY</b> .	CODE	DESCRIPTION				UNIT PRICE	PRICE
1		Labour	7			\$109.00	\$109.00
0	and Goodle al		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$109.00
Give us Feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTE MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MA		GST (5%):	\$5.45	
		INTEREST A	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$114.45		
		MATERIALS SETTLED, R RESULTING	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPC USTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AN FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERI E. & O. E. CUSTOMER SIGNATURE	NSIBLE FOR BROKEN, D ANY OTHER DAMAGES			