

🕒 @SimplyPlumbing 🛛 🚹 YaletownPlumbing

HST #837181627

DATE 2018-03-28	TECHNICIAN Darren Mann		JOB/ORDER # 8335		REFERENCE TEXT Client reference
FIRST NAME Rob		LAST NAME McLean	7		
BILLING ADDRESS COMPANY / BILLING NAME 1807 - 939 HOMER ST VANCOUVER, V6B 2W6 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 1807 - 939 HOMER ST, BUZZE VANCOUVER, V6B 2W6 BRITISH COLUMBIA, CANADA	
PHONE 604.816.2231				EMAIL robmclean@me.com	

REASON FOR TODAY'S CALL:

For a pedestal bathroom sink. the waste pipe appears to be leaking slightly just after the P-trap before the pipe goes into the wall.

DESCRIPTION OF WORK PERFORMED:

-I removed the portion of the trap that was leaking, it seemed to be in good shape so I cleaned it up and applied permatex to the inside of the coupling before reinstalling. This stopped the leaking. -During testing I noticed the drain was backing up. I used the PowerSpin drain snake to clean the drainage and tested by filling and draining the sink multiple times. No other leaks detected.

QTY .	CODE			DESCRIPTION	UNIT PRICE	PRICE	
1		Clean drain using PowerSpin / Lavatory				\$139.00	\$139.00
Current Goodle al				PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS. THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY		SUBTOTAL:	\$139.00
Give us Feedback Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your					GST (5%):	\$6.95	
		TOTAL:			\$145.95		
<u>Tha</u>	<u>rk Yoi</u>	<u>u!</u>	SETTLED, RU RESULTING	LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT USTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OL FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, M . & O. E. CUSTOMER SIGNATURE	ITS AND ANY OTHER DAMAGES 3.		