



DATE 2018-04-06	TECHNICIAN Darren Mann	JOB/ORDER # 8359	REFERENCE TEXT Client reference
FIRST NAME Barbara		LAST NAME LaVan	
BILLING ADDRESS COMPANY / BILLING NAME 6142 GLENEAGLES DRIVE VANCOUVER, V7W1W3 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1502 - 1280 RICHARDS ST BUZ#00740 PARIS LAVAN 604.880.2393 PARIS.LAVAN@GMAIL.COM VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.921.7106		EMAIL barbaralv@shaw.ca	

REASON FOR TODAY'S CALL:
 broken glass in garburator. *Max(concierge) will grant access.

DESCRIPTION OF WORK PERFORMED:
 I removed the broken glass from the garburator grinding chamber and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$109.00
GST (5%):	\$5.45
TOTAL:	\$114.45

_____ 2018-04-06
 CUSTOMER SIGNATURE DATE