

🕒 @SimplyPlumbing 🛛 🚹 YaletownPlumbing

HST #837181627

DATE 2018-04-18	TECHNICIAN Darren Mann		JOB/ORDER # 8385		REFERENCE TEXT Client reference
FIRST NAME Faye		LAST NAME Tassioulas	7		
BILLING ADDRESS COMPANY / BILLING NAME 406 - 988 RICHARDS ST VANCOUVER, V6B8R2 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 406 - 988 RICHARDS ST, BUZZ VANCOUVER, V6B8R2 BRITISH COLUMBIA, CANADA	
PHONE 778.227.0412				EMAIL faye.tassioula@gmail.com	

REASON FOR TODAY'S CALL:

Sink cartridge is leaky Garburator or pipe is leaking water... started only when garburator was in operation, now it leaks a portion of the water that drains

DESCRIPTION OF WORK PERFORMED:

-I replaced the leaking garburator with a new Waste King 1001 and tested by filling and draining the sink multiple times while running the garburator. -I replaced the leaking kitchen faucet cartridge(K35A) and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	1	Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00
1	6	K35a Cartridge	\$75.00	\$75.00
0	Concerts - Subject to MANUFACTURER'S WARRANTY			
Gwe us Feedback Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your invoice and tell us how we did. <u>Thank Youl</u>		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$17.70
			TOTAL:	\$371.70
		VE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTI ED. RUSTED DETERIORATION OR LEAD PIPES ELTURES CLEAN QUITS AND ANY OTHER DAMAGES.		/

CUSTOMER SIGNATURE

2018-04-18

DATE