

2018-04-26

DATE

HST #837181627

DATE 2018-04-26	TECHNICIAN Darren Mann	No.	JOB/O 8417	RDER#	REFERENCE TEXT Client reference	
FIRST NAME Jeremy		LAST NAME Yang	97			
BILLING ADDRESS COMPANY / BILLING NAME 202 - 1835 BARCLAY ST VANCOUVER, V6G 1K7 BRITISH COLUMBIA, CANADA	4		Ly,	SERVICE ADDRESS  202 - 1835 BARCLAY ST, BUZ VANCOUVER, V6G 1K7 BRITISH COLUMBIA, CANADA		
PHONE 778.865.3935				EMAIL jeremy293@yahoo.com		

## REASON FOR TODAY'S CALL:

My garburator is busted. Just want to get rid of it as I don't use it or need it. No need to replace it.

## DESCRIPTION OF WORK PERFORMED:

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	7/	Delete Garburator & Re-Pipe ABS Drainage	\$219.00	\$219.00
<u> Lino</u>	, 115 G	eedback warranty: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$219.00
	it our feedbac	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS  K page at:  MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOL	, ,	\$10.9
Fill in the required details from your invoice and tell us how we did.  Thank You!			TOTAL:	\$229.9
		WE did.  MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES  MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FO  SETTLED BUSTED DETERIORATION OR LEAD RIDES SIXTURES OF EACH OUTS AND ANY OTHER	AND R BROKEN, ER DAMAGES	

CUSTOMER SIGNATURE