



DATE 2018-04-27	TECHNICIAN Darren Mann	JOB/ORDER # 8420	REFERENCE TEXT Client reference
FIRST NAME Faye		LAST NAME Tassioulas	
BILLING ADDRESS COMPANY / BILLING NAME 406 - 988 RICHARDS ST VANCOUVER, V6B8R2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 406 - 988 RICHARDS ST, BUZZER 1028 VANCOUVER, V6B8R2 BRITISH COLUMBIA, CANADA	
PHONE 778.227.0412		EMAIL faye.tassioula@gmail.com	

REASON FOR TODAY'S CALL:  
Pressure dropped in kitchen faucet.

DESCRIPTION OF WORK PERFORMED:  
The hot & Cold shut off valves under the kitchen sink (connected to the faucet) were breaking down, causing bits of rubber from within the shut off valves to clog up the faucet spray head. I repaired the hot and Cold shut off valves by replacing the washers, stems, packing, packing nuts, and handles. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Repair 1/2" x 3/8" Angle or Straight Stop	\$139.00	\$139.00

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

\_\_\_\_\_ 2018-04-27  
 \_\_\_\_\_  
 CUSTOMER SIGNATURE DATE

SUBTOTAL:	\$139.00
GST (5%):	\$6.95
TOTAL:	\$145.95