

HST #837181627

DATE 2018-05-08	TECHNICIAN Darren Mann		JOB/O 8459	RDER #	REFERENCE TEXT Client reference
FIRST NAME Jason		LAST NAME Wong	97		
BILLING ADDRESS COMPANY / BILLING NAME 1801 - 1483 HOMER ST VANCOUVER , V6Z3C7 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS 1801 - 1483 HOMER STREET VANCOUVER , V6Z3C7 BRITISH COLUMBIA, CANADA	
PHONE 604.338.3348				EMAIL Joeshoegg1234@hotmail.com	

REASON FOR TODAY'S CALL:

Clogged bathtub

DESCRIPTION OF WORK PERFORMED:

I used the PowerSpin drain snake to clear hair from the ensuite bathroom tub drain. Tested by filling th tub 8? and draining. I also cleared hair from the guest bathroom tub drain(no charge).

TECHNICIAN RECOMMENDATIONS:

The grout between the tiles around the ensuite tub is falling out. I highly recommend having a tile guy in to regrout as water could potentially find its way in behind the the tile.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Clean drain using PowerSpin / Tub/Shower	\$139.00	\$139.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			SUBTOTAL:	\$139.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$6.95
			TOTAL:	\$145.95

Thank You!

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2018-05-08

CUSTOMER SIGNATURE

DATE