

🕒 @SimplyPlumbing 🛛 🚹 YaletownPlumbing

HST #837181627

DATE 2018-05-11	TECHNICIAN Darren Mann		JOB/ORDER # 8468		REFERENCE TEXT Client reference
FIRST NAME dirk		LAST NAME smith	7		
BILLING ADDRESS COMPANY / BILLING NAME 206 - 1050 SMITHE ST VANCOUVER, V6E4T4 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 206 - 1050 SMITHE ST BUZZER: 1060 VANCOUVER, V6E4T4 BRITISH COLUMBIA, CANADA	
PHONE 604.341.4724				EMAIL 1800das@gmail.com	

REASON FOR TODAY'S CALL:

toilet tank float mechanism needs repair bathtub faucet needs secure thru access panel

DESCRIPTION OF WORK PERFORMED:

-I replaced the toilet fillvalve, flapper, and supply line. Tested and in good working order. -I was able to resecure the Roman tub filler spout by tightening the nut underneath.

QTY.	CODE			DESCRIPTION	UNIT PRICE	PRICE	
1		Replace Toilet Fill\	t FillValve, Flapper, Supply - Standard				\$169.00
Gwe us Feedback			WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUT WARRANTY ON CUSTOMER SUPPLIED MATERIALS. THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS		SUBTOTAL:	\$169.00
Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your invoice and tell us how we did. <u>Thank You!</u>					GST (5%):	\$8.45	
					TOTAL:	\$177.45	
		MATERIALS L SETTLED, RU RESULTING F	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT R ISTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUT FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, M/ . & O. E.				
				CUSTOMER SIGNATURE	DATE		